

Oil Field Environmental Incident Summary

Incident: 20161008170808

Date/Time of Notice: 10/08/2016 17:08

Responsible Party: WHITE ROCK OIL & GAS, LLC

Well Operator: WHITE ROCK OIL & GAS, LLC

Well Name: BIG STICK (MADISON) UNIT 3610

Field Name: BIG STICK

Well File #: 6995

Date Incident: 10/7/2016

Time Incident: 17:00

Facility ID Number:

County: BILLINGS

Twp: 142

Rng: 101

Sec: 36

Qtr:

Location Description:

Submitted By: Travis White

Received By:

Contact Person: Travis White
5001 SPRING VALLEY RD
SUITE 100 E.
DALLAS, TX 75244

General Land Use: Badlands Terrain

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	6	Barrels	6	Barrels		

Description of Other Released Contaminant:

Oil & Brine Mixture

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Top soil.

Areal Extent:

Some runoff into a ditch. It is estimated to be 50-75' from source and no wider than 5 ft.

Potential Environmental Impacts:

Soil contamination will need to be removed.

Action Taken or Planned:

Isolated wells while Precision built a 15x15 dike around the source of the leak. A vac truck was called immediately and recovered 5 bbls but had a mechanical issue. Subsequently, 1 bbl could not be recovered. Contaminated soil will be removed and replaced.

Wastes Disposal Location: TBD.

Agencies Involved: USFS

Updates

Date: 10/10/2016 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Date: 10/13/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 15:20, 10/13/2016.

Site currently being remediated with the impacted material being stacked on tarps awaiting disposal. The contaminants flowed down the ditch to the west approximately 100 yards before terminating.

More follow-up is necessary to ensure proper cleanup.

Date: 10/18/2016 **Status:** Inspection

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 11:49, 10-18-16. It was sunny and cold. There was a pile of contamination surrounded by a soil berm and a partially blown away tarp. The impacted area also included the ditch which showed no signs of contamination. Further follow-up is needed to ensure proper cleanup.